


Drawings

MODEL 701944/ 701945

100:1 Probe

Unit : mm
(approx. inch)



Note: 1. Be sure to support the instrument from the bottom.
2. Provide a clearance of at least 80mm around the instrument for ventilation.

If not specified, the tolerance is $\pm 3\%$. However, in cases of less than 10 mm, the tolerance is ± 0.3 mm.