User's Manual

SL1000 Acquisition Software Version Upgrade Procedure

Foreword

This user's manual describes the procedure for upgrading the version of the SL1000 acquisition software and the firmware of the SL1000 Data Acquisition Unit. Please be sure to follow this user's manual when upgrading the version of the SL1000 acquisition software or firmware.

Trademarks

- Microsoft, Windows, and Windows XP are trademarks or registered trademarks of Microsoft Corporation in the United States and/or other countries.
- Adobe, Acrobat, and PostScript are trademarks or registered trademarks of Adobe Systems Incorporated.
- The company and product names used in this manual are not accompanied by the trademark or registered trademark symbols (TM and ®).
- Other company and product names are trademarks or registered trademarks of their respective companies.

Disclaimers

Yokogawa will accept no responsibility for damage caused directly or indirectly as a result of use of the product.

Before Starting the Version Upgrade

Decompress the downloaded file. The compressed file contains the following.

- Setup.exe (SL1000 acquisition software installer)
- Firmware folder (SL1000 unit firmware)
- SL1000 folder (SL1000 acquisition software related files)
- Xviewer folder (Xviewer related files)
- Recovery folder (SL1000 unit recovery tool)
- YKMUSB folder (USB driver)
- SL1000 software release notes -***_**.txt (where *** is the version of the acquisition software or firmware)
- User's manual

CAUTION

- When upgrading the version of both the SL1000 acquisition software and the firmware, you
 must first upgrade the SL1000 acquisition software.
- Files in the Firmware and Recovery folders are not installed on the PC by the acquisition software installer. If needed, save them on the PC prior to the version upgrade by copying the folders to the PC.
- How to install the USB driver, refer to the User's Manual in YKMUSB folder.



Procedure for Upgrade

The following is the procedure for performing the version upgrade.

Note_

The version number displayed below is only an example. Be sure to check that your upgraded version number is correct.

Acquisition Software Version Upgrade

1. Run the decompressed Setup.exe file. Select the application(s) to install, then start the version upgrade. See the SL1000 acquisition software user's manual (720120-61E) for the installation procedure.




2. When installation is finished, start the SL1000 acquisition software. On the Help menu, click About, then check that the latest version of the SL1000 acquisition software is displayed.

About S	_1000	
9	SL1000 Acquisition Software Version 2.13 Copyright (C) 2007-2010 Yokogawa Electric C	OK Corporation.

3. If you installed Xviewer (other than /XV0), click **About Xviewer** on Xviewer's Help menu, then check that the latest version of Xviewer is displayed.

This completes the version upgrade of the SL1000 acquisition software.



SL1000 Data Acquisition Unit Firmware Version Upgrade

To perform a version upgrade of the SL1000 Data Acquisition Unit (hereinafter, *the SL1000*) firmware, you must connect the PC onto which the version upgrade software was downloaded to the SL1000 via USB or Ethernet. Therefore, the PC used for the version upgrade must already have the SL1000 acquisition software installed on it.

 Right-click the shortcut to the SL1000 acquisition software located on the desktop, click Properties, then click the Shortcut tab. At the end of the string in the Target box, type the "-v" (version upgrade) startup option (including quotation marks).

SL1000 Proper	ties 🔹 🛛 🛛 🔀	
General Shorto	ut Compatibility	
🛐 SL	1000	
Target type:	Application	
Target location:	SL1000	
<u>I</u> arget:	ram Files\Yokogawa\SL1000\SL1000.exe	Type "-v" here
<u>S</u> tart in:	"H:\Program Files\Yokogawa\SL1000\"	
Shortcut <u>k</u> ey:	None	
<u>R</u> un:	Normal window	
Comment:		
<u>F</u> ind	Target Change Icon Advanced	
	OK Cancel Apply	

- 2. Connect the PC and the SL1000 via USB or Ethernet, then start the SL1000 acquisition software. See the SL1000 acquisition software user's manual (720120-61E) for the connection procedure.
- **3.** If the versions of the SL1000 and the SL1000 acquisition software do not match (NG is displayed if the combination does not allow control), the screen below is displayed allowing you to upgrade the firmware version. If this screen does not appear, skip to step 6.

Update Firmware							
The unit of the previous version is detected, and it cannot be operated. It is necessary to update the firmware. Download the latest firmware from the following URL, select the downloaded folder, and click the Update button.							
Unit ID	Firmware	State					
0	F2.03	NG					
Download URL http://www.yokogawa.com/tm/SL1000/							
Folder							
Note) The unit under the measurement stops measuring when updating it.							
Updat	e	Cancel					

4. Click the browse button, and select the Firmware folder that was downloaded and decompressed.

Update Firmware			
The unit of the previous	version is detected, an	d it cannot be operated.	
It is necessary to updat from the following URL, Update button.			
Unit ID	Firmware	State	
0	F2.03	NG	
Download URL <u>http://</u>	www.yokogawa.com/tr	n/SL1000/	Path the "Firmware" folder
Folder D:/Fit	mware/		
Note) The unit under the	e measurement stops me	easuring when updating it.	
Updat	e	Cancel	

5. Click the Update button. The firmware version upgrade executes. During the upgrade, be sure not to turn OFF the power to the main unit. If the version upgrade is successful, the state changes to OK, and the message in the figure is displayed. Turn OFF the power to the main unit, then restart it (if for some reason the restart is not successful, please see the firmware upgrade user's manual in the Recovery folder).

After the unit restarts, proceed to step 8.

Update Firmw	vare	X	
It is necessary t	o update the firmware. D	ed, and it cannot be operated. ownload the latest firmware baded folder, and click the	
Unit ID	Firmware	State	
0	F2.03	ок 	
Download URL	http://www.yokogawa.	.com/tm/SL1000/	
Folder	D:/Firmware/		
Update is compl	ete. Reboot the unit for th	e changes to take effect. ———	- Message
	Update	Done	

If the Version Mismatch Screen in Step 3 Is Not Displayed

6. Open the Self Test screen from the **Environment** menu, then click the **Service** tab. Click the browse button, and select the Firmware folder.

2	elf Test					X	
	Unit ID 0	•					
	Self Test Service	Unit Info.					
	Update Firmware (sl1000.bin,	Folder D:/Firmwar	e/		Transfer		
	main.rbf, pci.rbf)			Transfe	r (ALL Units)		

7. Click the Transfer button to execute the firmware version upgrade. During the upgrade, be sure not to turn OFF the power to the main unit. If the version upgrade is successful, the messages in the figure below appears. Turn OFF the power to the main unit, then restart it (if for some reason the restart is not successful, please see the firmware upgrade procedure manual in the Recovery folder).

SL1000	
1	The file transfer has finished successfully. Reboot the unit for the changes to take effect. sl1000.bin main.rbf pci.rbf
	()

Checking the Version

8. Close the SL1000 acquisition software. To ensure that firmware is not mistakenly overwritten, remove the "-v" startup option that was added in step 1.

Start the SL1000 acquisition software. Open the Self Test screen from the **Environment** menu, then click the **Unit Info** tab. Check that the firmware is of the latest version.

Self Test	0 -		×	
	iervice Unit Info.			
Firmware		F2.07 —		— Firmware version
FPGA FPGA	ACQ PCI	1.1.13 1.1.46		
Slotl Slot2				
Slot3 Slot4				
Slot5 Slot6				
Slot7 Slot8				
Serial No.		91GC42524		
,				
			Close	