


Drawings

CL420


Clamp-on Process Meter

Unit : mm
(approx. inch)

<Main Unit>



<Clamp sensor>



If not specified, the tolerance is $\pm 3\%$. However, in cases of less than 10 mm, the tolerance is ± 0.3 mm.