


Drawings

CT1000A AC/DC Current Sensor

Unit: mm
(approx. inch)



()*: Auxiliary (reference) dimension

Weight: approx. 1.3 kg

If not specified, the tolerance is $\pm 3\%$. However, in cases of less than 10 mm, the tolerance is ± 0.3 mm.