


Drawings

99031


1 to 5V Adapter Set

Unit : mm
(approx. inch)


Input terminal adapter



Lead cables
(Red and Black)



Measurement leads
(Red and Black)



No.	Part No.	Remarks
<1>	B9638BP	Without 250Ω resistor
<2>	L4059PS	Red
<3>		Black
<4>	B9944UA	Red
<5>	B9944UB	Black

If not specified, the tolerance is $\pm 3\%$. However, in cases of less than 10 mm, the tolerance is ± 0.3 mm.